
Stand-Up Brackets

Side Mounting / Side Mounting, Dowel Hole / Side Mounting, Compact



+0.021

For mating, g6, f8 shaft tolerances are recommended. For Stand for Posts, see P2143 and P2144. Tightening with a long wrench is recommended.

CLTS is applicable up to D=30, and CLPK and CLPM are available from D=20 and up.
D=16 of CLTBM is not available.



CLTB CLPK
CLTM CLPM

CLTBM

CLTB35

Features: Compact Stand-Up Brackets 25 ~ 30% shorter in height, and approximately 10% narrower in width compared to standard Side Mounting Type (P.2157).

M8-35, 2 pcs



Part Number			^	В		-	_	G	ĸ	h	н	Е	4	d ₁	7	MA	w	Included	Unit Price				
Type	D _{H7}		Α	В		'	Г	G	,	111	п	-	u	uı		IVIA	VV	Screw	CLCB	CLCNM	CLCBM	CLCAM	CLCS
CLCB	20	+0.021	60	30	45	12	45	18	6.6	22	15	30	6.6	11	6.5	M6	2	M6-12, 1 pc.					
CLCNM	25		73 83	45	53] 12	54	30	9	27	18	35						M6-25, 1 pc.					
CLCBM	30			45	60		64	30	J 9	30	21	45	9	14	9	M8	2	M8-35, 1 pc.					
CLCAM	35	. 0 005	94	60	68	15	72	35	11	35	24	50						M8-40, 1 pc.					-
CLCS	40	+0.025	104	00	76		82	33	11	38	27	60	11	17.5	11	M10		M10-45, 1 pc.					-
CLCB CLCNM CLCBM CLCAM CLCS (D20~30)	50	U	118	75	87	18	94	45	14	43	33	70			' '			M10-50, 1 pc.					-


The tolerance and perpendicularity of DH7 are before slitting.
For mating, q6, f8 shaft tolerances are recommended. For Stand for Posts, see **P.2143** and **P.2144**. Tightening with a long wrench is recommended.



Part Number CLCB35

Stand-Up Brackets

Side Mounting, Casting, Dowel Holes / Slotted Holes



+0.015

10

M8-40, 2 pcs.

M10-45, 2 pcs.

1 -2158


The tolerance and perpendicularity of DH7 are before slitting.

● For mating, gc, f8 shaft tolerances are recommended. For Stand for Posts, see P.2143 and P.2144. Tightening with a long wrench is recommended.
● D=30 or less are applicable to CLPBD and CLPMD.



Side Mounting, Casting,

CI PRD





1 -2157